

COMPLIMENTARY BOARD RESOURCE | 2026 EDITION

The Building Envelope: A Board's Waterproofing and Leak-Prevention Guide

How roofs, balconies, windows, sealant joints, stucco, and below-grade systems work together, where they fail, and how Central Florida boards can stop water before it becomes a structural and mold crisis.

FOR COMMUNITY ASSOCIATION MANAGERS | HOA & CONDO BOARD MEMBERS
CENTRAL FLORIDA

This guide is a general educational resource for Florida community association boards and community association managers. It does not constitute legal, engineering, or financial advice. Building performance data, service-life ranges, and cost figures are general industry references and will vary by project, climate zone, product, and installer. Always consult a licensed Florida professional engineer and a qualified attorney for your specific obligations.

Gavin Sederopoulos
Vice President of Sales
Office (407) 744-9122
elementbiz.com

COMPLIMENTARY BOARD RESOURCE

What's Inside This Guide

Nine plain-English sections plus eight ready-to-use board tools, written for CAMs and board members who need to understand the building envelope as a system and act before water wins.

1 **The Envelope as a System**
Why all six layers work together, and why water is the building's primary adversary

2 **Where Envelopes Fail**
Roofs, balconies, windows, sealant joints, stucco, expansion joints, below-grade

3 **From Leak to Structural Damage and Mold**
How water travels, what it destroys, and why the real source is rarely obvious

4 **The Maintenance Calendar**
Annual and seasonal tasks that keep the envelope performing

5 **Coatings, Sealants, and Systems**
Elastomeric coatings, traffic membranes, flashing, sealant chemistry, and service life

6 **Leak Diagnosis and Inspection**
Water testing, infrared thermography, and finding the real leak source

7 **The Cost of Water Intrusion**
What deferred maintenance actually costs, with real numbers

8 **Case Story: When Deferred Waterproofing Becomes a Collapse**
A documented Florida example and the lessons for every board

9 **How ESS Fits and What to Do Next**
ESS's envelope and waterproofing capabilities, and a complimentary on-site inspection offer

A **Appendix: Eight Board Tools**
Checklist, calendar, scorecard, log, RFP language, reserve worksheet, leak-source decision tree, and recoat tracker

Three Actions to Take This Month

- Walk every balcony, expansion joint, and window head on your building with a flashlight. Flag any cracked or missing sealant, rust staining, or efflorescence and document them in the Leak-Tracking Log in the appendix of this guide.
- Pull the last sealed engineer's report or milestone inspection report and confirm whether waterproofing, sealants, or coating systems were flagged. If so, verify that each finding has a written status and a timeline for correction.
- Review your current reserve study: confirm that sealant joints, roof membrane, and balcony deck coatings are each funded as their own line item. The Structural Integrity Reserve Study requires these components to be separately tracked and non-waivable.

DISCLAIMER

This guide is a general educational resource. It does not constitute legal, engineering, financial, or professional advice. Service-life ranges, cost figures, and maintenance intervals are general industry references and vary by product, exposure, application quality, and climate. Verify all obligations with licensed Florida professionals and qualified legal counsel.

SECTION ONE

The Envelope as a System

01

Six interdependent layers, one shared mission: keep water out of the building structure.

The building envelope is not a single component. It is the sum of every surface and joint that separates the conditioned, occupied interior from the exterior environment. When boards think of waterproofing as a roof problem or a window problem, they miss the point: the envelope fails as a system, and a weak link in any layer eventually pulls the others into failure.

The Six Layers of the Building Envelope

1. Roof Assembly

The primary horizontal barrier. Flat or low-slope roofs on Central Florida condominiums are typically single-ply membranes (TPO, EPDM, modified bitumen), built-up systems, or spray polyurethane foam. Failure here sends water into the top floor and eventually into the structural deck.

2. Balconies and Elevated Decks

Every elevated walking surface is a potential water entry point. Balcony slabs drain (or fail to drain) onto structural concrete. Traffic-grade waterproof membranes and correct slope are non-negotiable in Florida's high-rainfall environment.

3. Windows and Doors

The window-to-wall interface, specifically the installation flashing, head condition, and sill sealant, is among the most common leak sources in multi-story buildings. The glazing unit itself rarely fails first; the installation perimeter does.

4. Sealant Joints

Caulk and sealant at control joints, expansion joints, and penetrations are the most frequently overlooked envelope component and the one with the shortest service life. Most sealant joints require replacement every 10 to 15 years. When they fail, water enters behind the cladding system.

5. Exterior Cladding (Stucco and Coatings)

Stucco and EIFS cladding systems are not waterproof by themselves. They are drainage planes, designed to shed bulk water while the sealant joints and flashing behind them handle secondary moisture. Cracked stucco without intact sealant is an open entry point.

6. Below-Grade Systems

Foundation walls, below-grade parking structures, and elevator pits rely on crystalline or membrane waterproofing, drainage board, and proper soil grading. Hydrostatic pressure from Florida's high water table makes below-grade failures especially damaging.

1. Milestone Inspection (**FS 553.899**) is a one-time structural safety check.
2. SIRS (**FS 718.112(2)(g)**) is an ongoing, non-waivable funding requirement.
3. Both apply to condos/co-ops (Ch. 718/719) only, not to a standalone-home HOA (Ch. 720).

MILESTONE INSPECTION VS. SIRS: NOT THE SAME REQUIREMENT

Boards frequently conflate these two obligations. The **Milestone Inspection** is a one-time structural safety check, performed by a licensed engineer or architect, that flags substantial structural distress requiring repair. The **Structural Integrity Reserve Study, or SIRS**, is a separate, ongoing funding requirement: it identifies specific building components, including waterproofing and the building envelope, that must each be reserved for individually and funded on a non-waivable basis. A building can pass its Milestone Inspection with no structural distress flagged and still be out of compliance on SIRS funding for its envelope components.

Both requirements apply to condominiums and cooperatives (Chapters 718/719); neither applies directly to a standalone-home HOA under Chapter 720 unless a specific building within that HOA is itself legally organized as a condominium. Confirm your building's status with your association attorney before assuming either requirement applies or does not apply.

What This Means for Your Board

Do not treat a clean Milestone Inspection as proof your envelope reserves are adequately funded. They are two different questions, answered by two different documents, on two different schedules. Ask your reserve specialist to confirm both separately at your next SIRS update.

RELATED GUIDES IN THIS SERIES

For the full Milestone Inspection and SIRS requirements, deadlines, and reserve-funding math, see **Milestone Inspection & SIRS**. For the multi-year reserve capital plan behind a properly funded envelope line item, see **Reserve & Budget Planning**.

Why Water Is the Building's Primary Adversary

Among the forces that degrade a concrete and steel structure, water is the most pervasive and the most deceptive. It moves through hairline cracks too small to see, travels horizontally inside wall assemblies, and can migrate several feet from the entry point before manifesting inside the building. By the time an interior stain appears, water has typically been present in the structure for months.

In Florida's environment, water brings two additional weapons: chlorides from coastal air that corrode embedded steel, and the near-constant humidity that sustains mold growth in any cavity where moisture accumulates. The combination accelerates deterioration well beyond what the original structural design anticipated.

1. Water intrusion is widely cited by the AIA and construction-defect attorneys as involved in an estimated **70% of cases**, an industry consensus figure, not a single hard statistic.

2. Over **50%** of commercial property insurance claims trace back to water damage of some kind.

3. Nearly **1 in 4** U.S. homeowner insurance claims involve water damage or freezing (Insurance Information Institute, 2023).

Water Intrusion: The Dominant Loss Driver

Across three independent measures, water is the leading source of building losses.



of building-defect litigation involves water intrusion

of commercial property claims trace to water damage

homeowner insurance claims involve water or freezing

Sources: AIA and construction-defect practitioner consensus (70% is an industry-consensus estimate, not a single study); industry commercial-claims data; Insurance Information Institute (2023).

WHAT THIS CHART SHOWS

For a board or CAM, this means the single highest-leverage investment in loss prevention is maintaining the building envelope, not reacting after the first stain appears.

SECTION TWO

Where Envelopes Fail

02

The seven most common failure points in Central Florida multi-story buildings, and the warning signs boards can spot without a contractor on site.

Roofs

Flat and low-slope roofs in Central Florida fail at laps, penetrations, and perimeter flashings before the field membrane shows visible damage. A membrane can look intact from a rooftop walkthrough while perimeter edge and penetration details actively leak.

Warning signs: stains on top-floor ceilings, bubbling or alligatoring membrane, open lap seams, rusted flashings, missing pipe boot collars.

Balconies and Elevated Decks

Balcony slabs are subject to chloride infiltration from rainfall and coastal air. Water enters through failed traffic coatings or slab cracks. Once inside the slab, moisture corrodes embedded rebar; rust expansion spalls the concrete from within. The soffit is where this damage first becomes visible.

Warning signs: rust staining on soffits, spalling or delamination of concrete underside, deck cracks holding water, missing sealant at the wall-to-balcony joint.

Windows and Doors

The most common leak point is the installation perimeter: head flashing, sill pan, and frame-to-wall sealant. Wind-driven rain in high-rise applications forces water through gaps that would not leak under gravity alone.

Warning signs: interior staining at window heads or sills, efflorescence below windows on exterior wall, visible sealant gap at the frame, peeling paint at window corners.

Sealant Joints

Control joints, expansion joints, and penetration sealants are the shortest-lived envelope components. Most polyurethane sealants have a designed service life of 10 to 15 years under Florida sun exposure. When they harden, crack, or debond, water enters behind the cladding.

Warning signs: cracked or missing sealant at control joints; sealant pulling away from one or both substrates; chalky or powdering sealant surface.

Stucco and EIFS Cladding

Stucco and EIFS are not waterproof surfaces. They are rain-screen systems designed to drain bulk water. When sealant joints fail and stucco develops horizontal cracks, water penetrates and becomes trapped between the stucco and the substrate, leading to wall cavity moisture, mold, and structural sheathing damage.

Warning signs: diagonal cracks at window corners, horizontal cracks at floor-to-floor lines, efflorescence indicating active moisture movement, soft or hollow areas when tapped.

Expansion Joints

Buildings move. Expansion joints are engineered gaps that allow thermal movement and minor settlement without cracking the structure. The filler systems inside those joints, neoprene, foam backer, and sealant, deteriorate. When an expansion joint fails, it fails completely: water enters, and the repair requires removing and replacing the entire joint assembly.

Below-Grade

Parking garages and below-grade foundations are subject to hydrostatic pressure. Florida's water table is high. Crystalline or sheet-applied waterproofing systems on foundation walls require intact drainage board and functional perimeter drains to perform.

Warning signs: efflorescence (white mineral deposits) on concrete walls, active seeping or damp patches after rainfall, mottled staining at construction joints, standing water in elevator pits or low points.

RED FLAG: EXPANSION JOINT FAILURE IS TOTAL FAILURE

Unlike a sealant joint that can be partially compromised, an expansion joint that has failed must be replaced in its entirety, from end to end of the joint run. Partial patching of an expansion joint filler system is not a durable repair and will not restore the joint's ability to move with the building. Budget for the full assembly: backer, filler, and cap or cover system, as a capital line item.

What This Means for Your Board

Each of these seven failure modes follows a predictable sequence: small defect, deferred maintenance, water entry, structural damage, large repair cost. The warning signs listed above are visible to any board member or CAM with a flashlight and a phone camera. A photo log of flagged conditions, organized by building elevation and floor, is the foundation of a defensible maintenance record and the first step toward a repair priority list.

SECTION THREE

From Leak to Structural Damage and Mold

03

How water travels through a building assembly, the hidden damage it creates before anyone notices, and why the visible stain is almost never the real problem.

The Water Travel Path: Balcony-to-Wall Cutaway

Water entering a building envelope does not fall straight down from the entry point to the interior. It follows the path of least resistance through the building assembly, which means it travels along structural members, behind cladding, through cracks in the concrete substrate, and inside wall cavities before appearing on a ceiling or wall surface. In multi-story concrete buildings, water can migrate 10 or more feet laterally from where it entered before showing up inside a unit. The diagram below traces one common path: a failed balcony-to-wall sealant joint that lets water travel sideways into the wall cavity, well away from where the stain eventually shows up inside the unit.



Illustrative diagram, not an engineering drawing. Actual assembly details, cavity depth, and drainage paths vary by building and must be confirmed by a licensed professional.

This migration path is why leak investigations are difficult and why fixing only the visible symptom almost always leads to a repeat call. The water stain on the tenth floor may trace back to a failed window sealant on the twelfth floor, or to a missing expansion joint cap three feet to the left of where the stain appears.

The Deterioration Sequence in Concrete Buildings

STAGE 1 - ENTRY
Water enters through a failed sealant joint, crack, or membrane breach. No interior evidence yet. The building's drainage plane handles incidental moisture, but sustained entry overwhelms it.

STAGE 2 - SATURATION
Concrete and masonry absorb moisture. Chloride ions from rain and coastal air begin migrating toward the embedded reinforcing steel. This stage can last years with no visible symptoms.

STAGE 3 - CORROSION INITIATION
Chloride concentration at the rebar surface exceeds the threshold and active corrosion begins. Rust occupies greater volume than the original steel, generating expansive pressure inside the concrete.

The Deterioration Sequence (continued)

STAGE 4 - CRACKING AND SPALLING

Expansive pressure from corrosion cracks the concrete cover. Spalling (chunks of concrete separating from the slab) follows. Rust staining appears on soffits and exterior faces. This is the first stage most boards notice.

STAGE 5 - STRUCTURAL LOSS AND MOLD

Rebar section is reduced by corrosion. Load-carrying capacity decreases. Simultaneously, mold colonizes any wet organic material (framing, drywall, insulation) within wall assemblies, creating health and remediation obligations.

MOLD GROWS IN 24 TO 48 HOURS

Mold spores colonize wet building materials within 24 to 48 hours of water contact, according to U.S. Environmental Protection Agency (EPA) guidance. A leak that goes unaddressed over a weekend can establish mold inside a wall cavity before a maintenance call is even placed. Florida's heat accelerates growth further. Mold remediation in a commercial building costs $15 to $30 per square foot and is disruptive to occupants, often requiring temporary displacement and creating ongoing documentation obligations under Florida Statutes.

What This Means for Your Board

The five stages above are not a warning about a rare event. They describe the normal trajectory of an untreated leak in a Florida concrete building. Stages 1 through 3 are invisible. The board sees Stage 4, by which point the repair cost is typically 10 to 15 times what it would have been at Stage 1. The only lever the board controls is catching the entry point early, before saturation begins.

SECTION FOUR

The Maintenance Calendar

04

Annual and seasonal envelope inspection and maintenance tasks that extend component life and catch failures before they become structural repairs.

Timing	Task	Why It Matters
Pre-Hurricane Season (April to May)	Full sealant joint inspection at all control joints, window perimeters, and expansion joints. Probe for hardness, cracking, and adhesion loss.	Recaulking before June 1 is the highest-return envelope maintenance task.
Pre-Hurricane Season (April to May)	Roof membrane inspection by a licensed roofing contractor. Check penetrations, edge metal, and lap seams. Clear all drains and scuppers.	Blocked drains create ponding that exceeds design load; a hurricane can then breach a borderline-serviceable membrane.
Post-Hurricane Season (November)	Balcony-by-balcony visual inspection. Look for new cracking, spalling, or delamination on soffits. Document with photos and unit numbers.	Catching damage early allows planned repair instead of emergency response.
Post-Hurricane Season (November)	Review building-wide leak reports from the past 12 months. Map reported locations against the building elevation to identify clusters.	Clustering reveals whether a problem is systemic or localized.
Annual (dry season)	Pressure-wash all balconies and walkways. Inspect coating on clean surfaces; flag areas worn to bare concrete.	Exposed concrete is an active chloride entry point. Recoating is far less costly than structural slab repair.
Annual	Confirm elastomeric wall coating on all stucco and EIFS. Look for peeling, crazing, or adhesion loss. Check warranty period against installation date.	Recoating at the warranty boundary prevents underlying sealant failures from going unaddressed.
Every 5 to 7 Years	Full sealant replacement program for all exterior joints as a capital project.	Running sealants to failure guarantees water entry before replacement is complete.
Every 10 Years	Building envelope assessment by a licensed Florida PE. Coordinate with SIRS and milestone inspection cycles.	Documents maintenance history for defense in any future claim.

What This Means for Your Board

Most boards respond to leaks. High-performing boards prevent them. The difference is a written calendar in the meeting minutes, with each task assigned to a named vendor or staff member and confirmed complete in writing.

SECTION FIVE

Coatings, Sealants, and Systems

05

The materials that protect the building envelope, how they perform in Central Florida's climate, and service-life data for reserve planning.

Elastomeric Wall Coatings

Elastomeric coatings are thick-film, flexible acrylic or polyurethane formulations applied over stucco, concrete, or EIFS. They bridge hairline cracks while repelling bulk water but are not substitutes for sealant joints at control joints and penetrations. Typical service life: **10 to 15 years**. Recoating at the warranty boundary is best practice.

Traffic Coatings (Balcony Deck Membranes)

Traffic-grade membranes for balconies and parking decks are typically polyurethane or polyurea systems over a crack-bridging basecoat with an aggregate topcoat for slip resistance. Standard warranties run **5 to 10 years**; advanced PUMA formulations achieve **up to 20 years**. As the primary waterproofing barrier over occupied space, failure has immediate structural consequences.

Sealant Chemistry

The three principal sealant categories for envelope work, with service life ranges that vary by exposure and product line (see Section 5's sealant chart for the full comparison):

- **Silicone:** Best UV resistance and flexibility; not paintable; best at glass-to-frame interfaces. Approximately 20+ years exterior.
- **Polyurethane:** Best all-around performance at control joints and window perimeters. Paintable, adheres well to concrete and stucco. Approximately 10 to 20 years.
- **Polysulfide:** Strong resistance to submersion and chemical exposure; common at pool decks. Approximately 15 to 20 years.

Roof Membrane Systems

The three dominant systems for flat and low-slope roofs in Central Florida:

- **TPO:** Heat-welded seams, reflective surface. Service life: **20 to 25 years** (NRCA). Susceptible to lap failures if seams are not welded by certified applicators.
- **EPDM:** Synthetic rubber, flexible at all temperatures. Service life: **20 to 30 years** (EPDM Roofing Association survey, n=569). Adhered systems outperform mechanically attached in high-wind environments.
- **Modified Bitumen:** Multi-ply SBS or APP modified asphalt. Service life: **15 to 20 years**. Reliable in Florida with proper drainage slope.

Flashing Systems

Flashing directs water away from joints, penetrations, and transitions. At roof-to-wall transitions, window heads, and parapet caps, flashing must lap correctly, be fully adhered or mechanically fastened, and terminate with a compatible sealant bead. A flashing failure is rarely visible until water has already entered.

Below-Grade Waterproofing

Crystalline waterproofing compounds penetrate concrete and seal capillary pores. Sheet-applied membranes (HDPE, bentonite) provide a physical barrier. Both require intact drainage board and functional aggregate drainage to perform under hydrostatic pressure.

Service Life by Envelope Component: Reserve Planning Reference

The following ranges represent typical manufacturer warranty periods and industry-reported service lives. Central Florida's UV intensity, rainfall, and coastal exposure generally put buildings at the shorter end of these ranges. Use the lower bound as the planning cycle unless a specific product and maintenance history warrant otherwise.

Service Life by Envelope Component

Typical manufacturer warranty and industry-reported service-life ranges, in years.



Sources: NRCA (TPO/EPDM); EPDM Roofing Association 2025 survey (n=569); manufacturer warranty data (Tremco, Sika, Pecora); industry coating literature.

WHAT THIS CHART SHOWS

Exterior paint has the shortest cycle (5 to 7 years) and is the most commonly skipped item. Flat roof membranes have the longest service life (20 to 25 years) but the highest replacement cost. **The most common underfunded components in Central Florida are sealant joints (no separate reserve line) and traffic coatings (combined with general balcony repair).**

Envelope Component	Typical Service Life	Primary Failure Mode in FL	Reserve Category
Exterior paint	5 to 7 years	UV fading, chalking, adhesion loss	Operating or reserves
Joint sealants (polyurethane)	10 to 15 years	UV hardening, thermal crack, adhesion failure	Capital reserve (separate line)
Elastomeric wall coating	10 to 15 years	UV degradation, crack bridging failure	Capital reserve
Traffic coating / balcony deck membrane	10 to 20 years	Delamination, abrasion, ponding failure	Capital reserve (SIRS component)
Flat roof membrane (TPO/EPDM)	20 to 25 years	Penetration failure, lap separation, mechanical damage	Capital reserve (SIRS component)

Sources: NRCA (TPO/EPDM); EPDM Roofing Association 2025 survey (n=569); manufacturer warranty data (Tremco, Sika, Pecora); industry coating literature.

What This Means for Your Board

Compare these service life ranges against your most recent reserve study. If sealant joints do not appear as a separate line item, or if traffic coatings and roof membrane are combined into a single "exterior maintenance" bucket, flag it for your reserve specialist at the next update. The SIRS requires individually tracked line items for these components, and a lumped budget routinely results in underfunding.

CENTRAL FLORIDA ADJUSTMENT

Florida's UV intensity, high annual rainfall in the Orlando metro area, hurricane-season wind-driven rain, and coastal chloride exposure push most envelope components toward the shorter end of published service life ranges. Reserve studies based on national averages commonly overestimate remaining useful life for Florida buildings. When in doubt, use the lower bound of the range as your planning cycle.

Sealant Service Life by Chemistry

Not all sealants perform the same in Florida's UV and heat exposure. The chemistry you specify has a direct effect on how many years a joint stays watertight before it needs replacement.

Sealant Service Life by Chemistry

Typical exterior service life in Florida UV and heat exposure, by sealant chemistry.



Industry service-life ranges (W.R. Meadows; ASTM C920 Class 50-100 for silicone). Actual life varies by exposure, movement, and installation quality.

WHAT THIS CHART SHOWS

Silicone sealants offer the longest typical exterior service life, roughly 20 or more years in ASTM C920 Class 50-100 products, but are not paintable and are best reserved for glass-to-frame interfaces. Polyurethane sealants (10 to 20 years) remain the workhorse for control joints and window perimeters because they are paintable and adhere well to concrete and stucco. Polysulfide sealants (15 to 20 years) hold up best under submersion and chemical exposure, making them the standard choice at pool decks. **Match the chemistry to the joint's actual exposure, not just the lowest bid, and the sealant program will outlast a single board's term.**

What This Means for Your Board

When comparing bids, confirm the sealant chemistry specified matches the joint's actual exposure. A polyurethane sealant quoted at pool-deck submersion joints, or a non-paintable silicone quoted at a visible control joint, is a sign the bidder did not walk the building before pricing.

Warranty Tracking: What Voids a Warranty, What to Request at Closeout

A waterproofing or coating warranty is only as good as the paperwork behind it. Boards routinely discover a warranty is void at the exact moment they need it, after a leak, when a manufacturer's field inspection reveals a condition that breached the terms years earlier.

Common Warranty Voiders

- Applying a coating or sealant over an incompatible prior product without a documented compatibility test
- Skipping or shortcutting the specified surface preparation (dwell time, profile, moisture testing)
- Under-thickness application below the manufacturer's minimum dry-film mil requirement
- Using an unapproved installer not certified by the manufacturer for that product line
- Standing water or ponding left unaddressed on a warrantied traffic coating
- Unrelated later work (roofing, railing anchors, signage) penetrating the warrantied membrane without a manufacturer-approved detail

What to Request at Project Closeout

- The manufacturer's warranty certificate, naming the association, with start date and term stated in writing
- The contractor's separate labor warranty, with term and scope stated in writing
- Product data sheets and lot/batch numbers for the specific materials installed
- Applied mil-thickness verification records (wet-film or dry-film gauge readings) taken during installation
- Photos of surface preparation and each coat, dated and tied to the specific elevation or zone
- A copy filed with the association's permanent records, not just the property manager's inbox

What This Means for Your Board

Warranty documentation is worthless if nobody can find it when a claim is needed. Assign a specific board member or the CAM to maintain a warranty binder, physical or digital, for every envelope project. Tool 8 in the appendix gives you a standing tracker for exactly this purpose.

SECTION SIX

Leak Diagnosis and Inspection

06

Water testing, infrared thermography, and the methodical process of tracing a leak to its actual source, not just where it shows up inside the building.



Surface preparation and close-up inspection are prerequisites for accurate leak diagnosis. Cleaning reveals crack patterns, sealant condition, and staining that weathered surfaces conceal.

Why Standard Visual Inspection Misses Most Leaks

A visual inspection can identify symptoms: stains, efflorescence, visible cracks. It cannot identify the source. Water that enters on the twelfth floor can travel along the structural slab and manifest on the tenth floor with no visible connection to the entry point above it. Addressing only the symptom location is a reliable way to spend repair dollars without fixing the problem.

Diagnostic Methods

Controlled Water Testing (ASTM E1105)

A licensed engineer or envelope specialist applies water to a defined area of the exterior using a calibrated nozzle at the pressure and flow rate specified by ASTM E1105. By systematically testing one zone at a time (window perimeter, wall field, head flashing, then sill), the source is isolated to a specific detail. This is the definitive test for window and wall leaks and is commonly required by courts in construction defect litigation.

Infrared Thermography

Wet building materials retain heat differently than dry materials. An infrared camera captures the temperature differential, showing moisture patterns behind surfaces without destructive testing. Surveys are most accurate after dark or early morning after rainfall, and can cover large facade areas quickly.

Flood Testing

For balcony decks and elevated slabs, flood testing involves temporarily damming the deck perimeter and filling it with a shallow water column for 24 to 72 hours. Water at the soffit below confirms membrane failure. This method is used for both diagnosis and post-repair verification.

Core Sampling and Probes

A licensed engineer may core through stucco and substrate to assess moisture content, condition of sheathing or waterproofing membrane, and evidence of past wetting cycles. Core samples in concrete can be analyzed for chloride content to gauge the risk to embedded rebar.

Ground-Penetrating Radar (GPR)

GPR maps embedded rebar, voids, and moisture distribution within a concrete slab without removing the surface. It is used on balcony slabs and parking decks to identify areas of corrosion activity or delamination before the surface shows symptoms, enabling targeted repair rather than full-slab replacement.

THE "DRIEST ROOF, WETTEST CEILING" PHENOMENON

The most common mistake in leak investigations is starting on the roof because that is where boards assume the water comes from. In most multi-story concrete buildings, roof leaks account for a minority of interior moisture complaints. Window and door installation failures, sealant joint failures, and wall penetration failures are statistically far more common causes of unit-level leaks. Start with the exterior wall at the level where the complaint originates, not the roof.

What This Means for Your Board

When a unit owner reports a leak, resist the impulse to send a roofer. The entry point is rarely directly above the stain. Engage a licensed envelope contractor or engineer who will test systematically: start at the exterior face of the wall at the complaint floor, test each detail in isolation, and confirm the source before recommending repair. A correct diagnosis, even if it costs $1,500 to $3,000, saves tens of thousands in misapplied repairs.

SECTION SEVEN

The Cost of Water Intrusion

07

What deferred waterproofing maintenance actually costs, in real numbers, and why the ratio of prevention to repair is the most important financial argument a board can make.

The Escalation Sequence

Water damage cost does not grow linearly. It escalates in steps that compound on each other. A failed sealant joint that would cost roughly $3,000 to replace as part of a routine program, if left unaddressed, enables water to reach the structural slab. At that point, the repair is no longer a sealant replacement: it becomes concrete removal, rebar treatment, patching, and recoating, commonly running $30,000 to $50,000 for a localized area. If the structural repair is also deferred or done incorrectly, the embedded steel continues to corrode and the repair scope can widen to hundreds of thousands of dollars per elevation. Champlain Towers South is the extreme, catastrophic end of this same escalation pattern, not a separate phenomenon: a 2018 engineering report estimated $9.1 million in repairs, and by 2021, as damage worsened, that estimate had grown to $16 million. See Section 8 for the full documented sequence.

The Escalation Sequence (Illustrative Range)

What the same water intrusion problem costs at each stage of neglect.



Illustrative order-of-magnitude range drawn from general Florida contractor and restoration industry pricing, not a single audited study.

WHAT THIS CHART SHOWS (ILLUSTRATIVE RANGE)

These figures are an illustrative order-of-magnitude range drawn from general Florida contractor and restoration industry pricing, not a single audited study. Typical sealant joint replacement as part of a planned program: on the order of $3,000 per elevation zone. Reactive structural concrete repair for a water-damaged balcony slab: commonly $30,000 to $50,000 and up. Mold remediation in an affected wall cavity or unit: $15,000 or more. **Even at the low end of these ranges, the reactive structural repair runs an order of magnitude above the sealant program that would have prevented it. Get an actual proposal for your building's specific conditions before budgeting a number.**

Additional Cost Categories Boards Frequently Undercount

Emergency Pricing Premium

Reactive repair in the aftermath of a hurricane or during an active leak investigation commands emergency pricing: mobilization fees, overtime, and limited competitive bidding. Industry sources cite post-storm emergency waterproofing rates running 2 to 3 times standard contracted pricing. A board with a proactive program avoids this premium entirely.

Displacement Costs

Water intrusion significant enough to affect habitability of units creates an association obligation to address the situation. Depending on lease arrangements and governing documents, displacement, rent abatement, or temporary housing costs may fall on the association.

Litigation and Defense Costs

Water intrusion is widely cited by the AIA and construction-defect attorneys as involved in an estimated 70% of cases. Associations that cannot demonstrate a documented maintenance program, with inspection records and repair histories, are in a materially weaker defense position than those that can show consistent envelope maintenance. Defense legal costs in Florida construction defect cases typically begin in the tens of thousands of dollars.

Insurance Premium Impact

Florida property insurance underwriters scrutinize building envelope condition in renewal underwriting. A building with documented deferred maintenance, unaddressed roof conditions, or prior water claims is a candidate for coverage reduction, exclusions, or non-renewal in a market that is already under pressure.

"A $3,000 sealant program can become a $50,000 concrete repair. Deferred maintenance never saves money; it borrows against the next board's budget at a very high interest rate."

SECTION EIGHT

Case Story: When Deferred Waterproofing Becomes a Collapse

08

The documented sequence at Champlain Towers South is the most consequential building envelope failure in Florida history, and every lesson it contains applies directly to Central Florida boards today.

DOCUMENTED CASE STUDY

Champlain Towers South, Surfside, Florida (2021)

What was documented: In October 2018, structural engineering firm Morabito Consultants submitted a report to the Champlain Towers South Condominium Association. The report stated in direct language: "The waterproofing below the Pool Deck and Entrance Drive as well as all of the planter waterproofing is beyond its useful life and therefore must all be completely removed and replaced." It further warned that the failed waterproofing was causing "major structural damage to the concrete structural slab below these areas" and that "failure to replace the waterproofing in the near future will cause the extent of the concrete deterioration to expand exponentially."

What made it worse: The pool deck had been constructed with the waterproofing membrane on a flat surface, with no slope to drain. Rainwater accumulated on the waterproofing and remained until it evaporated. Over decades, that standing water, combined with chloride infiltration from the oceanfront environment, saturated the concrete slab below the pool. The embedded steel corroded. The 2018 report identified new cracking radiating from areas that had previously been epoxy-injected, a direct sign of ongoing and accelerating deterioration. Ocean water was also observed intruding into the below-grade parking garage through the same degraded waterproofing system.

What the repair estimate did as the delay continued: Morabito's October 2018 report estimated the full scope of needed waterproofing and structural repairs at approximately $9.1 million. By 2021, as damage worsened, that estimate had grown to roughly $16 million, a re-estimate reflecting three additional years of untreated deterioration, not a one-time cost. The board did not complete the waterproofing and structural repairs before June 24, 2021, when the building's pool deck and tower collapsed at 1:22 AM, killing 98 people.

Sources: Morabito Consultants engineering report to Champlain Towers South Condominium Association, Inc., October 8, 2018 (filed in subsequent litigation and widely reported); NIST NCSTAR Champlain Towers South Collapse Preliminary Findings, 2025; Associated Press; Miami Herald.

DOCUMENTED CASE STUDY (CONTINUED)

Champlain Towers South, Surfside, Florida (2021)

What NIST confirmed: Preliminary findings from the National Institute of Standards and Technology (NIST NCSTAR), released in 2025, identified the pool deck as the most likely origin of the collapse. NIST cited the failed waterproofing, the flat-grade pool deck design, and decades of chloride-induced corrosion as contributing factors, consistent with what the 2018 engineer's report described as already urgent.

What the eventual settlement covered: Separately from the repair cost itself, the litigation that followed the collapse resulted in a $997 million settlement, the second-largest of its kind in Florida history, covering the 136-unit building's owners for their property loss and the families of the 98 people who died. That settlement figure is a legal outcome, driven by the scale of the loss of life and property, and should not be read as a multiple of the $9.1 million to $16 million repair estimate; the two numbers measure different things.

What this means for your board: The Surfside collapse was not a sudden event. It was the end of a deterioration sequence that a sealed engineering report had documented three years earlier and named as urgent, with a repair estimate that nearly doubled while the board deferred. The lesson is not that your building will collapse. The lesson is that a sealed engineer's report describing structural waterproofing as "beyond its useful life" is not a suggestion, and the cost of delay compounds while a board deliberates.

Three Questions This Case Raises for Every Central Florida Board

1. Does your most recent engineer's report or milestone inspection identify any waterproofing component as "beyond useful life" or "requiring immediate replacement"? If so, what is the written action status?
2. Are any balcony decks, pool decks, or elevated slabs on your property constructed without positive drainage slope? This is the specific design deficiency that allowed standing water to accelerate deterioration at Champlain Towers.
3. Is the full dollar value of any outstanding waterproofing work in your reserve study and current-year budget? A finding without funding is not a plan.

SECTION NINE

How ESS Fits and What to Do Next

09

ESS self-performs nearly all structural and envelope trades in house: one licensed contractor responsible for the full scope, not a general contractor subcontracting work to unknown subs.



ESS crews performing walkway surface preparation and coating in Central Florida, self-performed under a Florida CGC license.

What ESS Self-Performs for Building Envelope Work

- Balcony and elevated deck waterproof membrane systems
- Sealant joint inspection, removal, and replacement programs
- Concrete restoration: spall repair, crack repair, rebar treatment, patching
- Stucco repair, refinishing, and elastomeric coating application
- Pressure washing and surface preparation prior to coating
- Expansion joint system removal and replacement
- Below-grade waterproofing and drainage board installation
- Window and door flashing and sealant remediation
- Parking deck and drive-lane traffic coating systems
- Drainage system cleaning and repair (scuppers, floor drains, downspouts)
- SIRS-aligned scopes with detailed line-item breakdowns
- Coordination with licensed Florida professional engineers for Phase 2 repair scopes

Start with a Complimentary On-Site Inspection

ESS offers a complimentary on-site inspection for Central Florida community associations. We walk your envelope, document conditions with photos, and provide a specific proposal with a real number for any work we recommend, with no obligation. The inspection covers sealant joints, balcony decks, stucco and coating condition, flashing, and drainage, and we document findings in writing so your board has a baseline record.



Gavin Sederopoulos
Vice President of Sales | Florida Certified General Contractor CGC1533292
Office (407) 744-9122 | elementbiz.com | Central Florida

Tool 1 - Building Envelope Inspection Checklist

How to use: Print and carry during a quarterly property walkthrough. Check each item, note location and condition. Hand to vendor or engineer for follow-up on any flagged item.

Roof and Roof-to-Wall Transition

- ☐ Roof membrane: visible bubbling, alligatoring, or open seams?
- ☐ All roof drains and scuppers clear of debris?
- ☐ Parapet cap flashing intact, no open joints?
- ☐ HVAC curb base flashings sealed and adhered?
- ☐ Pipe boot collars present and sealed at all penetrations?

Balconies and Elevated Decks

- ☐ Traffic coating intact; no areas worn to bare concrete?
- ☐ No standing water visible 24 hours after rainfall?
- ☐ Soffit (underside): no rust staining or concrete spalling?
- ☐ Balcony-to-wall sealant joint intact; no gaps or cracking?
- ☐ Railing anchorages tight; no rust weeping at base plates?

Windows and Doors

- ☐ Frame-to-wall sealant at all window and door perimeters intact?
- ☐ No interior staining at window heads or sills?
- ☐ Exterior wall below windows: no efflorescence or staining?
- ☐ Head flashing visible and turned up behind cladding?

Sealant Joints and Expansion Joints

- ☐ All control joints visible and filled (no open gaps)?
- ☐ Sealant is flexible; not hard, cracked, or powdering?
- ☐ Sealant adhering to both sides of joint (no edge lift)?
- ☐ Expansion joint covers present and undamaged?
- ☐ Last sealant replacement date documented in records?

Stucco and Exterior Cladding

- ☐ No horizontal cracking at floor-to-floor lines?
- ☐ No diagonal cracks radiating from window corners?
- ☐ No efflorescence (white mineral deposits) on wall surface?
- ☐ Coating intact; no peeling, chalking, or loss of adhesion?
- ☐ No hollow or soft areas when tapped on stucco surface?

Below-Grade and Drainage

- ☐ Parking garage walls: no active seeping or efflorescence?
- ☐ Floor drains in garage functional and clear of debris?
- ☐ Grade at perimeter sloping away from foundation?
- ☐ Elevator pit: no standing water after rainfall?

> This checklist is a general visual screening guide only. Items flagged during a board or management walkthrough should be evaluated by a licensed Florida professional engineer or qualified contractor before any repair scope is determined. This is not a substitute for a formal engineering assessment.

Tool 2 - Annual Envelope Maintenance Calendar

How to use: Assign a responsible party (property manager, vendor, or board member) and a target completion date for each item. Note completion in board minutes. Repeat annually.

Month / Season	Task	Responsible Party	Completed
April to May (pre-hurricane)	Full sealant joint inspection; probe all control joints and window perimeters for hardness, cracking, or adhesion failure		
April to May (pre-hurricane)	Roof inspection by licensed roofing contractor: check all penetrations, edge metal, drains, and lap seams		
April to May (pre-hurricane)	Clear all roof drains, scuppers, and balcony deck drains of debris		
June to October (hurricane season)	Monitor for new water intrusion reports after each significant rain event; log location and unit number		
November (post-hurricane)	Full balcony-by-balcony visual inspection; document new cracks, spalling, or rust staining with photos		
November (post-hurricane)	Map all leak reports from the past year against the building elevation to identify clusters		
December to February (dry season)	Pressure-wash all balconies and walkways; inspect traffic coating condition on clean surfaces		
December to February (dry season)	Inspect elastomeric wall coating for peeling, crazing, or chalk. Note any areas of adhesion failure.		
Annual (any month)	Update leak tracking log with all new entries from the past 12 months		
Every 5 to 7 years	Full sealant replacement program for all exterior joints as a capital project		
Every 10 years	Building envelope assessment by licensed FL professional engineer; coordinate with SIRS and milestone inspection cycle		

Maintenance intervals are general industry references. Specific products, exposure conditions, and prior maintenance history may shorten or extend recommended cycles. Confirm intervals with the applicable licensed contractor or engineer for your building.

Tool 3 - Coating and Sealant System Comparison Scorecard

How to use: When evaluating competing waterproofing or coating bids, score each proposal on the criteria below. A higher total score indicates a more complete and defensible specification. Require each bidder to answer the specification questions in writing as part of bid submission.

Specification Criterion	What to Look For	Points (0–3)	Bidder A	Bidder B
Product name and manufacturer specified	Named product (not "or equal"). Manufacturer data sheet provided.	3		
Applied mil thickness stated	Dry and wet mil thickness specified per manufacturer's TDS. Aligns with warranty requirement.	3		
Surface preparation specified	ICRI or SSPC surface prep standard cited. Pressure wash PSI and dwell time stated.	3		
Primer system included	Compatible primer named. Not optional or allowance-based.	3		

Continued on next page (criteria 5 through 8 of 8).

Tool 3 - Coating and Sealant System Comparison Scorecard (continued)

Criteria 5 through 8 of 8. Score each item 0 to 3. Total all eight criteria for final score.

Specification Criterion	What to Look For	Points (0-3)	Bidder A	Bidder B
Number of coats stated	Basecoat, intermediate, and topcoat count specified. Not "as needed."	3		
Joint sealant detail included	Sealant type, backer rod, tooling, and adhesion specified for all joints in scope.	3		
Warranty type and term stated	Manufacturer warranty vs. labor warranty distinguished. Term in years stated explicitly.	3		
Flood or water test after installation	Post-application verification test (flood test, water test, or thermographic survey) included or available at stated price.	3		

Total possible score: 24 points. A proposal scoring below 16 lacks the specification detail needed for an apple-to-apple comparison. Require clarification before scoring bids against price.

> This scorecard evaluates specification completeness only. It does not evaluate contractor qualifications, license status, insurance, or price competitiveness. Use it alongside a full contractor vetting process before contract award.

Tool 4 - Building Leak-Tracking Log

How to use: Log every reported water intrusion event as soon as it is reported. Cluster entries by location to identify systemic patterns. Bring this log to every envelope assessment or engineering meeting.



Drainage system inspection and documentation support accurate leak tracking and proactive envelope management.

Date	Unit / Location	Floor	Description of Intrusion	Weather Condition	Assigned To	Closed Date

Cluster analysis tip: After each hurricane season, highlight all entries on the same floor or elevation. Three or more entries within a 3-floor vertical zone on the same facade typically indicate a systemic sealant joint or flashing failure, not isolated unit-level issues. That pattern is the trigger for a contractor or engineer assessment of that specific zone.

> This log is an internal management tool. It does not substitute for formal engineering documentation, licensed contractor inspection reports, or insurance claim records. Retain completed logs indefinitely as part of the association's maintenance history.

Tool 5 - Sample Waterproofing RFP Scope Language

How to use: Copy the applicable sections into your request for proposals. Fill in bracketed items for your property. Require all bidders to respond to each specification item in writing. A contractor who cannot or will not answer a specification question is not a qualified bidder.

Project: [Building Name and Address] | **Issue Date:** [Date] | **Bid Due:** [Date]

Scope Description

The Association requests proposals for [sealant joint replacement / balcony deck waterproof membrane replacement / exterior elastomeric coating application / other] for [describe building or elevation]. Work shall be performed by a Florida Certified General Contractor (CGC) or applicable specialty licensed contractor. The successful bidder shall self-perform all work; no sub-contracting of the primary waterproofing scope without written Association approval.

Required Specification Responses (all bidders)

- **Product:** State the manufacturer, product name, and product data sheet number for all primary waterproofing, coating, and sealant products proposed. Substitutions require written approval before bid submission.
- **Applied Thickness:** State the minimum dry-film mil thickness to be applied and how compliance will be verified in the field.
- **Surface Preparation:** Describe the surface preparation method and standard (e.g., ICRI CSP-3, pressure wash at minimum [PSI]). State dwell time before primer application.
- **Primer:** State whether a primer coat is included. Identify the primer by manufacturer and product name.
- **Joint Detail:** For sealant scopes, state the backer rod diameter, sealant type, and tooling method. For expansion joints, describe the full assembly (backer, filler, and cap system).
- **Warranty:** State the manufacturer's product warranty term and the contractor's labor warranty term separately. Identify what voids the manufacturer's warranty.
- **Verification:** Describe the post-application verification method the bidder proposes (flood test, ASTM E1105 water test, or infrared survey). State whether verification is included in the base bid or available as an add-alternate.
- **License:** Provide Florida license number, license type, and qualifier name. Confirm license is Current, Active on myfloridalicense.com as of bid submission date.
- **Insurance:** COI to be provided naming [Association Name] as additional insured. Minimum General Liability: [state minimum]. Workers' Compensation: statutory limits, all employees, no officer exclusions.

Evaluation Criteria: Proposals will be evaluated on specification completeness, product quality, contractor qualifications and references, warranty terms, and price. Lowest price is not the sole criterion. The Association reserves the right to reject any or all proposals.

> This is sample language for educational purposes only. Have your association attorney review the final RFP and any contract before issuance. Specific requirements may vary by project size, scope, and governing document provisions.

Tool 6 - Envelope Reserve and Budget Worksheet

How to use: Complete the worked example column first to understand the math. Then fill in the "Your Property" column using your building's actual data. Bring to your reserve specialist for integration into the formal SIRS.

Worked Example: 80-Unit, 8-Story Central Florida Condominium

Envelope Component	Estimated Replacement Cost	Service Life (Yrs)	Annual Reserve Contribution	Your Property Contribution
Exterior sealant joints (all elevations)	$85,000	12	$7,083 / yr	
Balcony traffic coating (80 balconies)	$120,000	15	$8,000 / yr	
Roof membrane replacement	$210,000	22	$9,545 / yr	
Elastomeric wall coating (all elevations)	$95,000	12	$7,917 / yr	
Expansion joint replacement	$40,000	20	$2,000 / yr	
Window/door sealant remediation	$30,000	12	$2,500 / yr	

Total annual envelope reserve contribution (example)	**$37,045 / yr**	_____	*Sum of annual contributions above*
Per-unit monthly contribution (example: 80 units)	**$38.59 / unit / mo**	_____	*Annual total ÷ 80 units ÷ 12 months*
Your property: total annual envelope reserve contribution		_____	*Fill in from your reserve study*
Your property: per-unit monthly contribution		_____	*Annual ÷ unit count ÷ 12*
Gap: is envelope reserve below the worked-example benchmark for your unit count?		_____	*If yes, flag for SIRS update*

Note: The worked example uses general Florida cost ranges for a mid-size 8-story building. Your actual costs will vary based on building size, perimeter, number of balconies, roof area, and local labor and material pricing. Use this worksheet as an order-of-magnitude check against your current reserve study, not as a substitute for a formal reserve study by a qualified reserve specialist.

> Reserve contribution calculations are the province of qualified reserve specialists, not this worksheet. The figures above are illustrative only. The SIRS requires a formal study by a qualified professional using current cost estimates for your specific building.

Tool 7 - Leak-Source Diagnostic Decision Tree

How to use: When a leak is reported, walk this sequence before calling a contractor. It routes you to the most likely source category so the right specialist gets the first call, not a roofer sent to a window problem or vice versa.

A unit reports water intrusion. Is the affected area directly under the roof (top floor or penthouse)?

- **YES** → **Start with a roof inspection: check membrane laps, penetrations, and edge flashing near that location.**
- **NO** → **Is there a balcony, deck, or exterior walkway directly above the affected area?**
  - **YES** → **Inspect the balcony traffic coating and the wall-to-balcony sealant joint above. Check the soffit for rust staining first.**
  - **NO** → **Is the stain located near a window or door, on any floor?**
    - **YES** → **Inspect the window or door perimeter sealant and head flashing first. This is the most common leak source in multi-story buildings.**
    - **NO** → **Source is not obvious from the interior symptom alone. Do not guess: engage a licensed envelope contractor or engineer for ASTM E1105 water testing or infrared survey. See Section 6.**

This decision tree narrows the FIRST place to look. It does not replace systematic testing. Water travels laterally inside wall assemblies (see Section 3's cutaway diagram), so a "likely" source identified here must still be confirmed by controlled water testing before repair work begins. Never authorize a repair based on this tool alone.

Tool 8 - Sealant and Coating Recoat Tracker

How to use: Log every sealant, coating, or membrane installation by zone as soon as the project closes out. Set a calendar reminder at the warranty boundary, not after a leak is reported. Pair every entry with the warranty documentation from Section 5's closeout checklist.

Zone / Elevation	Product / System	Installed	Warranty Term	Warranty Expires	Next Recoat Due	Status

Worked example row: Zone: South elevation balconies (12) | Product: Polyurethane traffic coating | Installed: 03/2024 | Warranty term: 10 yrs | Expires: 03/2034 | Next recoat due: 2032-2033 (inspect at year 8) | Status: Active, no issues at last inspection.

> Status column should read one of: Active, Inspect Soon (within 2 years of warranty expiration), Recoat Scheduled, or Overdue. A zone sitting in "Overdue" status with no scheduled work is a budget and liability exposure, flag it for the board at the next meeting.

Key Sources and References

Water Intrusion and Claims Data

Water intrusion share of construction defect litigation (70%): Architect Magazine, "When It Leaks It Pours"; Forum Forensics, "Damage Report: Water Intrusion." Commercial property insurance claim share (50%+): industry insurance data cited by iPropertyManagement.com and gitnux.org. Residential homeowner insurance claim share (24%): Insurance Information Institute, 2023 claim data, cited by iPropertyManagement.com Water Damage Statistics 2026.

Cost Escalation Data (Illustrative Range)

Sealant-to-structural-repair escalation figures are an illustrative order-of-magnitude range drawn from general Florida waterproofing and restoration contractor pricing; treat as directional, not an audited study. Mold remediation cost ($15 to $30 per square foot): HomeGuide.com Mold Removal Cost 2026; ATI Restoration, "How Much Does Mold Remediation Cost." Mold growth within 24 to 48 hours: U.S. Environmental Protection Agency, "Mold Prevention in Schools and Commercial Buildings." Emergency waterproofing pricing premium: general industry waterproofing contractor sources.

Service Life Data

TPO and EPDM roof service life (20 to 30 years): National Roofing Contractors Association (NRCA); EPDM Roofing Association 2025 survey of 569 roofing professionals. Traffic coating service life (5 to 20 years depending on system): Tremco Sealants, Sika, Zander Solutions, RJC Engineers. Sealant joint service life by chemistry: silicone approximately 20+ years, polyurethane approximately 10 to 20 years, polysulfide approximately 15 to 20 years, general industry ranges per W.R. Meadows and ASTM C920 test-method literature; manufacturer data (Pecora, Dow, Tremco). Elastomeric coating service life (10 to 15 years): East Valley Foam, deckflex.com, manufacturer warranty documentation.

Case Story: Champlain Towers South

Morabito Consultants engineering report to Champlain Towers South Condominium Association, Inc., October 8, 2018 (filed in subsequent litigation and widely reported). 2018 repair estimate ($9.1 million) and 2021 re-estimate ($16 million) as damage worsened: reported by NBC News and NBC Miami. NIST NCSTAR, Champlain Towers South Collapse Preliminary Findings, 2025. Legal settlement ($997 million covering the 136-unit building's owners and the families of the 98 people who died): Associated Press; Miami Herald; Winston & Strawn; Washington Post.

This guide is a general educational resource for Florida community association boards and community association managers. It does not constitute legal, engineering, financial, or professional advice. All figures and service-life ranges are general references and will vary by product, application, exposure, and maintenance history. Verify all statutory obligations and professional standards with licensed Florida engineers and qualified legal counsel. © 2026 Element Service Solutions. All rights reserved. Reproduction without written permission is prohibited.

Gavin Sederopoulos | Vice President of Sales
Florida Certified General Contractor CGC1533292
Office (407) 744-9122 | elementbiz.com